





Computer Comforts, Inc.
367 Columbia Memorial Pkwy.
Kemah, TX 77565-3187
(281) 535-2288 • Fax: (281) 488-4272
www.computercomforts.com

G2 ERGO LIFT ADJUSTMENT INSTRUCTIONS




VESA PLATE

KEYBOARD/MOUSE TRAY




TO ADJUST TENSION AND CALIBRATE ARM TO WEIGHT OF LCD MONITOR & KEYBOARD/MOUSE:

TURN KNOB RIGHT TO INCREASE TENSION;
TURN LEFT TO DECREASE TENSION [PLEASE NOTE - WHEN *DECREASING* TENSION, TURN KNOB TILL IT GETS SNUG, THEN PUSH DOWN ON KEYBOARD TRAY 2" TO 4" (TO RESET), THEN REPEAT UNTIL DESIRED TENSION IS REACHED].



IF VESA PLATE NEEDS TO BE ADJUSTED, YOU WILL NEED A 1/8" ALLEN WRENCH TO REMOVE 4 SCREWS SHOWN, THEN PLACE IN DESIRED HOLES/POSITION AND RE-ATTACH.



SUGGESTED WIRING/CABLE MANAGEMENT:

PLASTIC WIRING CONDUIT CAN BE ADDED TO CLEAN UP AND GANG CABLES TOGETHER. CONDUIT CAN BE PURCHASED AT GRAINGER INDUSTRIAL SUPPLY OR MOST AUTO PARTS STORES.

USE SMALL HOLES ON THE SIDES OF THE KEYBOARD PLATFORM TO WIRE TIE YOUR KEYBOARD/MOUSE CABLES TO.